		1 P. A. T. 141	
	And the state of t	DATE DISTR.	1 June 1953
A /B (ECT	Railing Mill Production of Nonferrous Metals for First Haif of 1953 (Medium Plate) / 25X1A	NO. OF PAGES	
VOULET VOULET		NO. OF ENCLS.	
NATE OF		SUPPLEMENT TO	

Approved For Release 2002/07/26: CIA-RDP80-00810A001300260009-0

JISSIF" MON

COUNTRY CONTAINS INFORMATION APPECTING THE DATIONAL DEPENDS OF THE PROPERTY OF

THES TO IMPUALITATEL INFORMATION

25X1A

25X1X

GOUNTE

For the first quarter of 1953, production in the rolling of nonferrous medium plate was as follows (all weights are in metric tons):

- that the quote estigned for the first quarter will be fulfilled
- b. Orders have been placed at the Helbzeuguerke Averhamer amounting to 500 tons in excess of the assigned moduction quota. Averhamer will probably emperience difficulty in fulfilling even its production quota because of the poor delivery of plate bar. At present it will be impossible through 1,000 nm. sheet at Averhammer because of a break in the roller chadis
- c. Orders have been placed at the Mechwelzwerke Olbernhau amounting to about 50 tons in crocess of the assigned projection quota. Olbernham is expected to fulfill these excess orders.
- 2. For the second quarter of 1953, plans for the production of nection plate of nonferrous metals are as follows:
 - a. Unlawer Hettriedt has a rolling queta of 2,750 tons. An effort at 1 be
 - b. Insufficient orders encurting to 753 tons were placed at the Halback gaverle Averhager by the former quota bearer Ministry for Machine Lagrange Excess orders not filled during the first querter will be carried over to
 - c. To date, orders anounting to only 2,800 tons have been placed at the Cock-Halzwerke (Thermhau. Pruever, two many orders for 3 cm. place have been placed.

 CLASSIFICATION
 SECRET

 STATE
 1/2
 NAVY
 NSF/B
 DISTRIBUTION

 ARMY
 1/2
 ARR
 1/2
 FBI
 OPR/EV
 X

25X1

Approved For Release 2002/07/26 : CIA-RDP80-00810A001300260009-0

- 2 -

3. The lettredt, Olbernhau, and Auerbarrier mills would experience no difficulty in rolling plate of 3 mm. thickness and over. Previous insufficient rolling of plate in this thickness was caused in each case by the speradic and insufficient deliveries of plate bar from the Maxhautte Unterwellenborn.